# 60th LG nvironmental Inside



# What's Wrong With This Pictur

- **Container Management (1.)**
  - Drums need to be placed on pallets to reduce exposure to the elements and to prevent rusting
- **Container Management (2.)**
  - Empty drums need to be marked "EMPTY" and must include a date so that it may be managed in a reasonable amount of time
- **Container Management (3.)**
  - Containers must be closed when not adding or removing materials




These findings above are all considered Major findings

**(1.) 22CCR 66265.173(b)** - a container holding hazardous waste shall not be opened, handled, transferred or stored in a manner which may rupture the container or cause it to leak

**(2.) 40CFR 261.7** - containers larger than five gallons in capacity shall be managed within one year of being emptied

**(3.) 22CCR 66265.173(a)** - a container holding hazardous waste shall always be closed during transfer and storage, except when it is necessary to add or remove waste

**COMMON ECAMP FINDINGS**

1. Haz-Com Training Deficiency
2. HW Training Deficiency
3. Haz-Mat Storage
4. Improper Storage of HW
5. HW not Properly Labeled
6. Overdue Inspection
7. Improper Recycling Practices
8. Incomplete Contingency Plans
9. Exceeding HM Inventory
10. Failure to Maintain Spill Equipment

*Author: SSgt Robert DeLuca 60 CRS Unit Environmental Manager*
*OPR: TSgt William Burrage 60 LG Environmental Manager*